- (b) The labeling of the structural epoxy, previously mislabeled as reference number 111 in two separate locations, should be changed to reference numbers 114 and 116.
- (c) The labeling of the piezoelectric plate, previously mislabeled as reference number 116, should be changed to reference number 112.
- (d) The labeling of the epoxy layer, previously mislabeled as reference number 112, should be changed to reference number 116.

Applicants submit that no new matter has been introduced by these amendments.

Remarks

Figure 2B has been amended to change the conductive copper electrode layer, previously mislabeled as reference number 114, to reference number 111. Figure 2B as originally filed was inadvertently mislabeled. Support for this modification is found in the specification at, for example, page 16, line 19 and page 16, line 23.

Figure 2B has been amended to change the labeling of the structural epoxy layers, which previously were represented by reference number 111 in two separate locations of the drawing, to reference numbers 114 and 116. Support for this modification is found in the specification at, for example, page 16, lines 4-15, and page 16, lines 23-25.

Figure 2B has been amended to change the labeling of the piezoelectric plate, previously represented by reference number 116, to reference number 112. Support for this modification is found in the specification at, for example, page 16, line 17.

BEST AVAILABLE COPY